



POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION
VI

SITE NUMBER

TXD030171979

NOTE: The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A. SITE NAME Dresser Industries		B. STREET (or other identifier) 3400 W. Illinois Avenue	
C. CITY Dallas	D. STATE Texas	E. ZIP CODE 75211	F. COUNTY NAME Dallas 113

G. OWNER/OPERATOR (if known) L. NAME J. B. Kyle, General Manager		2. TELEPHONE NUMBER (214) 333-3211
--	--	---------------------------------------

H. TYPE OF OWNERSHIP (if known)					
<input type="checkbox"/> 1. FEDERAL	<input type="checkbox"/> 2. STATE	<input type="checkbox"/> 3. COUNTY	<input type="checkbox"/> 4. MUNICIPAL	<input checked="" type="checkbox"/> 5. PRIVATE	<input type="checkbox"/> 6. UNKNOWN

I. SITE DESCRIPTION:

The site is bordered by W. Illinois Avenue to the north, Coombs Creek to the west, Westmoreland Avenue to the east and the Santa Fe Railroad to the south. Entrance may be gained from W. Illinois Avenue or Coombs Creek Road. There is a guard house that must be passed before entering on-site. Also on-site is an office area, a manufacturing area, an inspection area and a storage area. The tank, sub-surface tank, two drum storage areas and the incinerator have been certified as closed. An affidavit of Exclusion was signed qualifying the facility for the "Accumulation Time" storage exclusion of Texas Administrative Code, Section 335.69. The site is located at latitude 32°43'05" N, longitude 96°52'30" W.

J. HOW IDENTIFIED (i.e., citizen's complaint, OSHA citations, etc.) Environmental Priorities Initiative	K. DATE IDENTIFIED (mo., day, & yr.) 4/21/89
--	---

L. SUMMARY OF POTENTIAL OR KNOWN PROBLEM

The following hazardous wastes are used or produced on-site:

- * Cyanide copper plating
- * Cyanide contaminated solids
- * Copper plating bath rinse
- * Wastewater treatment plant
- * Trichloroethylene
- * Toluene

No other potential problems have been identified at this time.

SUPERFUND FILE

JAN 29 1993

REORGANIZED

M. PREPARER INFORMATION

1. NAME Don L. Hudnall, FIT Toxicologist

2. TELEPHONE NUMBER

(214) 744-1641

3. DATE (mo., day, & yr.)

4/21/89

